

Sterling Rail, Inc.[°]

P: 512-263-1953 | F: 512-263-9799 | www.SterlingRail.com





FOR SALE

GP 40 Locomotive #4504

Inspection Report

- Car body is in good shape
- · Cab has good flooring, one seat missing
- One broken side window and front door widow broken
- Electrical cabinet has some Exaine wire and is called good condition by IN&P. Needs blowing out
- No missing parts
- · Unit has traction motor cut outs
- · Control stand -- nothing missing
- Batteries have 1.2 volts and are grounded, very dirty, low on water and corroding
- AR10 is dirty and oily. Floor around AR10 is covered with oil and wiring, cabling laying in it, could be grounded
- · Engine air filters very dirty
- Engine looks to be shut down running and top deck and air box are not as dirty as others
- Had 6 new power packs, 4 new heads, govenor, injectors 2002
- Replaced Turbo 2006
- No large oil leaks could be seen
- No Crankcase damage
- AC cabinet needs some help with wiring and cleaning noting missing
- This unit has the EC trans technologies APU same as the 4502
- Radiators have no visual signs of leaks, but hard to tell after 2 years in storage. They need to be pressure washed Fans all turn freely
- Dynamic Brake grids all look ok and fan turns freely. Has extended range DB
- 14 KW aux gem rebuilt 2007
- G.D. WBO deep sump air compressor
- Trucks look ok will need some brake shoes replaced before shipping
- Wheels all new in 2001 and are good condition very limited mileage
- · Unit has self aligning couplers
- Horn has been removed crossing bell in place
- Engine serial # 69-D-2R 16-567-D3
- Turbocharger serial # QT 032706-01

Price: \$160,000 Location: ID

FOR SALE

GP 40 Locomotive #4504

WORK SCOPE FOR IDAHO NORTHERN & PACIFIC LOCOMOTIVES

Blow out control stand and replace covers

Check all fluid levels, water, oil engine, air compressor, governor - 12-2-11

Blow out electrical cabinet front and rear Inspect fueling system for leaks. - 12-2-11

Visually inspect electrical cabinet wiring and relays for defects

Check exhausts system for leaks with engine running

Visually inspect main contactors for defects

Check air box for leaks

Blow out under cab floor Check operation of engine protective devices, low water, and low oil.

Change electrical cabinet air filter - 11-28-11 Check air brake system for leaks

Open AR 10 blow out and check fuses, clean inspection windows.

Check operation for horn and crossing bell

Check AC slip ring brushes Service traction motor support bearings - 11-26-11

Blow out Aux Gen and check brushes Service journal boxes - 11-26-11

Blow out and check brushes in DB motors

Service traction motor gear cases

Check brushes in fuel pump and turbo lube pump motors - 11-29-11 Check top of traction motors brush wear - 11-26-11

Check and clean AC cabinet Install new batteries - 11-18-11 installed new blocking - 11-29-11

Check operation of all lighting Replace all worn brake shoes - 11-26-11

Check operation of wheel slip system

Load unit in forward and reverse

Check operation of cab heaters

Other defects corrected

Check operation of emergency fuel cut offs

Both side battery box doors have broken hinges

Radiators should washed or blown out

Visually inspect engine for liner damage and broken rings - 12-2-11 12-1-11 - Tried to start APU but battery would not hold a charge, so

engine water.

Change spin on fuel filters - 11-29-11

Change 30 inch fuel filter - 11-11-11

Cleaned fuel strainer - 11-29-11 it was plugged, do not know how engine

ran above idle

Change all lube oil filters - 11-11-11

Changed TLOP sock back filter (both) - 12-1-11

Change engine air filters (baggies) - 1-11-11

12-2-11 - Started engine, it would not stay running without holding lay shaft, unplugged the governor and it would, but fuel pump would not stay ruining. Believe the "D" valve circuit is the problem, EFCO's seam to be

bought a new battery and got the APU running. Let it run all night to warm

working ok, I had no print and was alone, so when I can will trouble shoot

www.SterlingRail.com | info@SterlingRail.com