

Photo No. 1: Rear of Titan Trackmobile; fire damage to cab



Photo No. 2: Right side of Trackmobile; side where diesel engine is located



Photo No. 3: Front of Trackmobile



Photo No. 4: Left side of trackmobile



Photo No. 5: Battery box for Trackmobile; inside rear step; no arcing; batteries & connections intact



Photo No. 6: Fire damage to cab area of Trackmobile



Photo No. 7: Metal information tag for Titan Trackmobile




Photo No. 8: Hydraulic lines from Hydraulic Valve Block where operator controls engine remotely



Photo No. 9: Diesel engine's turbo charger & exhaust assembly; area of fire origin



Photo No. 10: Scanreco radio remote control used on Trackmobile prior to fire





PHOTO #3

Rear Rt Overall View



Description:

PHOTO #4

Rear Lt Overall View








PHOTO # 9

Rear View Of Damage



Description:

PHOTO #10

View Of Lt Side Damage



PHOTO #11

View Of Lt Side Damage



Description:

PHOTO # 12

View Of Rt Side Damage





PHOTO # 13


View Of Rt Side Damage




Description:

PHOTO #14

View Of Cab Damage












PHOTO # 23

View Of Damaged Engine



Description:

PHOTO #24

View Of Damaged Hydraulic Pump & Lines

