

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
4.00	G25105-0606	#6 TO PIPE	40.36	
1.00	201413	SPRING	8.28	
1.00	10J15	BALL 15/32'	0.66	
1.00	231822	RAIL VALVE	114.64	
1.00	232066	OIL SEAL	28.61	
1.00	246806	SOLENOID 12V SHIFTER	244.99	
2.00	G60470-0606	T FITTING	7.98	
2.00	G60470-0808	T- FITTING	10.38	
1.00	42469	Hydraulic tank breather	13.21	
2.00	15W40	15W40 M0TOR OIL	4.56	
5.00	ATF	TRANSMISSION FLUID	12.50	
1.00	ANTIFREEZE	ANTIFREEZE 4 L. JUGS	10.88	
1.00	8925274	VALVE COVER GASKET	34.57	
1.00	620500	AIR DRYER ASSY	863.62	
1.00	87515 INV	FLAT BAR 20'	13.00	
1.00	8D-MHD	BATTERY 12V 8D	174.95	
1.00	55014	switch toggle 2 blade	5.66	
1.00	8166-01	KNOBS	3.85	
1.00	73040	BACK UP ALARM	36.96	
1.00	12183	CONVEX MIRRIROR	18.50	
1.50	TGP114	SUPERIOR SHAFTING 1 1/4	6.38	
1.00	P181082	AIR PRMY	73.26	
1.00	P551670	ENGINE OIL FILTER	16.19	
2.00	TGP2	SUPERIOR SHAFTING	25.00	
1.00	P138722	AIR SAFETY	38.83	
14.00	15W40	15W40 M0TOR OIL	31.92	
1.00	P165314	HYD FILTER 441B CANISTER	32.56	
25.00	80W90	GEAR LUBE	58.75	
1.00	42469	Hydraulic tank breather	13.21	
1.00	9972994	BUSHING	14.57	
1.00	236645	TRANSMISSION OIL FILTER HOUSIN	0.00	
1.00	247055	FILTER ASSEMBLY	331.60	

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25
 FRONT AND 1600R25 REAR
 UNIT WEIGHTS 18520 KG OR 40830 LBS WITH
 GENERATOR NO MAGNET
 HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family,***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X _____
 Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	360-406	SENDER 400PSI	85.70	
1.00	350-110	OIL, 0-400 PSI DRIVE	49.85	
1.00	235	KIT UNLOADER VALVE TURBO 2000	39.97	
6.00	70607	HOSE #8	15.42	
26.00	ATF	TRANSMISSION FLUID	65.00	
1.00	9180	SWITCH	21.59	
1.00	2204037	TANK HEATER	90.34	
1.00	87466 INV	MISC STEEL PIECES	154.50	
1.00	23695	SEAL	34.90	
1.00	096-015	SPAENAUR 1 PK	52.19	
1.00	WLD600	FIRST AID KIT	26.52	
1.00	620500	AIR DYER ASSY TURBO 2000	595.60	
1.00	HOOK	HOOK 1 1/8" STOCK	5.00	
1.00	1037354	THIMBLE	5.18	
12.00	1835BK	3/8 FEMALE BODY H STYLE	134.52	
1.00	8D-MHD	BATTERY 12V 8D	202.95	
1.00	82757	AUXILLIARY POWER SOURCE	8.38	
12.00	1837BK	3/8 MALE PLUG H-STYLE	22.44	
1.00	EE-4629	TIE ROD END	58.82	
1.00	NNILC1	NYLON INSERT LOCKNUT 1"	2.68	
1.00	BG8C1-7	BOLT 1 X 7 BOOM TIP 441B	6.95	
1.00	8166-01	KNOBS	5.58	
1.00	G94511-0404	FITTING	5.02	
19.00	AW32	HYD OIL	58.14	
1.00	Decal kit	Decal kit	100.00	
30.00	70606	HYD HOSE #6	57.00	
34.00	70607	HYD HOSE #8	71.06	
5.00	70606	HYD HOSE #6	9.50	
9.00	G25170-0808X	8G-8FJX	49.32	
1.00	G25170-0806	8GE-6FJX HYD HOSE END	11.96	
2.00	762523	BATTERY TERMINAL -VE CU/TIN	18.44	
2.00	762524	BATTERY TERMINALS +VE CU/TIN	18.44	

<p>***** Thank You *****</p>	<p>We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***</p>	Labor	23,310.00		
		Parts	17,326.19		
<p>Service Recommendations</p> <p>ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3</p>	<p>I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.</p>	Inspection	0.00		
		Towing	0.00		
		Sublet	7,996.92		
		Shop Charge	0.00		
		Subtotal	48,633.11		
		H.S.T.	0.00		
		Amount Paid	0.00		
		Total Due	48,633.11		
		X _____	Received By		

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
13.00	15W40	15W40 MOTOR OIL	28.60	
2.00	G60181-0808	8FP-8FP-8FP	19.90	
2.00	G60152-0606	6FP-6FP 2096-06	3.50	
1.00	202821120485	CAB HEATER	1,995.95	
1.00	P562584	FILTER BREATHER	14.58	
1.00	8D-MHD	BATTERY 12V 8D	202.95	
1.00	STEEL	FUEL TANK BRACKETS	12.00	
1.00	16267 INV	NUMBER DECALS	25.00	
1.00	22 INCH	WIPER BLADE 22 INCH	7.92	
1.00	16 INCH	WIPER 16 INCH	7.37	
1.00	2986SY4040	OPERATORS MANUAL BOX	47.00	
1.00	452501121201099	STEEL RIM 11 1/4x25	1,195.00	
1.00	00245266 INV	CUSTOMS CHARGES	32.50	
1.00	38029INV	499-RC11031-2B CYL & FIT	1,908.20	
1.00	860008556INV	TIRE REPAIR	352.00	
1.00	75221-09	SWITCH, ROTARY, 3 POSITION, WI	30.13	
1.00	44437INV	HYDRAULIC FITTINGS	54.98	
1.00	101C	ANTIFREEZE - GREEN	14.43	
1.00	ef-abco5e	fire extinguisher	57.93	
1.00	25070INV	BACKGLASS	98.60	
1.00	247052	FILTER	65.57	
2.00	40X60X6DL	HIGH PRESSURE SEAL	30.00	
1.00	P181082	AIR PRMY	62.38	
1.00	G25179-0606	FITTING 90' FEMALE	8.80	
44.00	6G2	HOSE #6	104.72	
6.00	G25170-0608	6G-8FJX FITTING	28.20	
1.00	G25170-0606	6G-6FJX FITTING	6.99	
4.00	g60541-0806	fitting	33.00	
1.00	370064A	SEAL 445E PLANETARY	94.75	
1.00	5062598-00INV	REPLACE INJ/COMP TEST	2,170.32	
1.00	0283924INV	ADAPTORS	29.04	
1.00	53596INV	FITTINGS	54.98	

<p>***** Thank You *****</p>	<p>We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***</p>	<table border="1"> <tr><td>Labor</td><td>23,310.00</td></tr> <tr><td>Parts</td><td>17,326.19</td></tr> <tr><td>Inspection</td><td>0.00</td></tr> <tr><td>Towing</td><td>0.00</td></tr> <tr><td>Sublet</td><td>7,996.92</td></tr> <tr><td>Shop Charge</td><td>0.00</td></tr> <tr><td>Subtotal</td><td>48,633.11</td></tr> <tr><td>H.S.T.</td><td>0.00</td></tr> <tr><td>Amount Paid</td><td>0.00</td></tr> <tr><td>Total Due</td><td>48,633.11</td></tr> </table>	Labor	23,310.00	Parts	17,326.19	Inspection	0.00	Towing	0.00	Sublet	7,996.92	Shop Charge	0.00	Subtotal	48,633.11	H.S.T.	0.00	Amount Paid	0.00	Total Due	48,633.11
	Labor	23,310.00																				
Parts	17,326.19																					
Inspection	0.00																					
Towing	0.00																					
Sublet	7,996.92																					
Shop Charge	0.00																					
Subtotal	48,633.11																					
H.S.T.	0.00																					
Amount Paid	0.00																					
Total Due	48,633.11																					
<p>Service Recommendations</p> <p>ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3</p>	<p>I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.</p> <p>X _____ Received By</p>																					

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	48238INV	HYDRAULIC FITTINGS	183.71	
1.00	499	THROTTLE AIR CYLINDER	168.00	
1.00	360-406	PRESSURE SENDING UNIT	77.15	
1.00	P550928	SECONDARY FUEL FILTER	6.31	
1.00	P550936	FILTER FUEL	7.00	
1.00	P181082	AIR PRMY	60.16	
1.00	74048	TRANS PRESSURE GAUGE	43.27	
1.00	73328	TRANS PRESS SENDING UNIT	73.17	
1.00	52490P/S	COMPRESSOR OIL LINE	133.52	
1.00	G25179-0404	FITTING 90' FEMALE	11.20	
1.00	G25170-0404	FITTING 4G- 4FJX	4.74	
1.00	4G2	HOSE #4 HYD 2 WIRE	1.90	
2.00	26392	adp 1-34"x2"	17.44	
2.00	IN00097323	LIGHT SWITCH	22.96	
1.00	G25170-0404	FITTING 4G- 4FJX	4.97	
1.00	1NS018655INV	MOVE CENTRE OF RIM	674.77	
1.00	26513	UPPER RAD HOSE	50.51	
1.00	43735INV	YELLOW SPRAY PAINT	136.80	
1.00	43787INV	SPRAY PAINT	136.80	
7.00	4G2	HOSE #4 HYD 2 WIRE	21.07	
1.00	G25181-0404	FITTING LONG 90' #4	14.00	
1.00	041564INV	SOLENOID VALVE & MANIFOLD	92.16	
1.50	4140176	AFT ULTRALUBE EP D3M (20L-5G)	4.65	
1.00	43928INV	PRIMER & YELLOW SPRAY PAINT	187.80	
2.00	53052	LAMP PEDESTAL 2 WIRE BLACK	33.26	
1.00	382824INV	AIR VALVE/WHEEL NUTS	129.85	
1.00	TYRS100	1" NPT DIVERTER VALVE	128.47	
1.00	200ZM12V-AM	Strobe Light 12VDC Amber	84.48	
1.00	59454INV	HYDRAULIC FITTINGS	35.63	
1.00	102449INV	1/2" PLATE 16X18-1/2"	55.00	
1.00	J009618	CLAMP BAND	15.55	
1.00	280EE-F	TEMP SENDER 350*	50.82	

<p>***** Thank You *****</p>	<p>We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***</p>	Labor	23,310.00		
		Parts	17,326.19		
<p>Service Recommendations</p> <p>ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3</p>	<p>I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.</p>	Inspection	0.00		
		Towing	0.00		
		Sublet	7,996.92		
		Shop Charge	0.00		
		Subtotal	48,633.11		
		H.S.T.	0.00		
		Amount Paid	0.00		
		Total Due	48,633.11		
		X _____	Received By		

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	280ED-F	TEMP SENDER 280*	36.05	
1.00	9115	SWITCH MOMEMTARY NC	6.66	
1.00	0031144INV	THERMOSTAT & GASKET	17.50	
1.00	P550936	FILTER FUEL	6.93	
1.00	P550928	SECONDARY FUEL FILTER	6.27	
1.00	P551670	FILTER OIL	13.77	
2.00	4140176	AFT ULTRALUBE EP D3M (20L-5G)	6.20	
2.00	LL-6015-4	KIT, SEAL (FOR AL-10448-2)	101.24	
1.00	LL-1994-386	KIT, REPAIR (FOR LL-1994-384)	31.32	
1.00	74850	TAPERED CUP	134.50	
1.00	74550	TAPERED CONE	201.49	
16.00	500005764	AW32 HYDRAULIC OIL	39.84	
2.00	6-5TSLWH	5 Ton Swivel Hook w Latch	69.02	
1.00	73040	BACK UP ALARM	22.24	
2.00	74850	TAPERED CUP	269.00	
2.00	74550	TAPERED CONE	402.98	
1.00	LL-3811-63	KIT, GAP REPAIR	123.38	
	Marc L	08/02/2013		100.00
	Nick C	THROTTLE REPAIR		140.00
	Richard L	08.15.12 PRIME AND PAINT VARIOUS AREAS-INSTALL DECALS		120.00
	Eric	08.21.12 REPLACE WINCH WIRE ROPE INSTALL 5/8"X150'		80.00
	Nick C	08.10.12 WORK ON UNIT		60.00
	Harold F	08.10.12 PREP FOR PAINTING		90.00
	Bill Sto.	08.10.12 SPEEDSWING ANNUAL INSPECTION		160.00
	Greg B	04.06.10 INSTALL CAB HEATER		80.00
	Bill Sto.	12.29.09 WORKED WITH ERIC ON 360 SPEEDSWING		80.00
		04.07.10 FINISH INSTALLING CAB HEATER		

***** Thank You *****

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25
 FRONT AND 1600R25 REAR
 UNIT WEIGHTS 18520 KG OR 40830 LBS WITH
 GENERATOR NO MAGNET
 HRS JAN 24/2012 2398.3

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
 Received By

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Gary M.	07.13.09 HOOK UP WIRING FOR AIR DRYER HEATER. INSTALL BUSHING IN LEVER. INSTALL LEAVER AND LINK. INSTALL TRANSMISSION FILTER AND FILTER HEAD. FILL TRANSMISSION. INSTALL WHEEL STUD. LOOK AND FIND LIMIT SWITCH ARM.		320.00
	Carl	03.31.10 WORK WITH GREG-REPLACE ORING ON HYDRAULIC SOLENOID FOR A/C SYSTEM. REPAIRED GROUND WIRE TERMINAL -REPLACED. TEST A/C SYTEM FOR OPERATION & LEAKS FROM VALVE-OK		40.00
	Rick P.	07.10.09 PUT TURBO 2000 AIR KIT IN BACK OF MACHINE		160.00
	Rick P.	03.28.11 SPEED SWING BOOKS		20.00
	Carl	04.16.10 INSTALLED FRONT STEERING CYLINDERS. DISASSEMBLED REAR MASTER CYLINDER FOR LEAK REPAIR. INSTALLED FRONT HOOK WITH CODLER ASS'Y. WELD AND REPAIR P CLAMP BOLT AND COUPLER MOUNT TO TOTE BOOM FOR CLAM HYDRAULIC HOSES. GET GENERATOR RUNNING. GET MAGNET WORKING. REPLACED REAR MASTER CYLINDER ASSEMBLY BLEED BRAKES. TEST MAGNET AND HYRAILS ON TRACK. INSTALL DECALS.		340.00
	DERICK L.	08.21.12 CUT PLATE AND WELD FOR WINCH INSTALLATION		140.00
	DERICK L.	02.13.12 REMOVE CLAM AND HYDRAULIC HOSES		40.00
	DERICK L.	04.26.11 FABRICATE HEATER BRACKET AND PRIME + PAINT		40.00
	Eric	02.28.11 RECHECKED PLANETARY ENDS, OIL LEVEL STARTED UP SPEEDSWING, REMOVED PARK BRAKE ROD. REMOVED PARK BRAKE DRUM ON PARKBRAKE TO ACCESS LEAKING PINION SEAL. REINSTALLED WIRING HOLDER INSIDE OF CAB. REMOVED REAR STEER CYLINDER PIN & BUSHING TO MATCH REPLACEMENT and CLEAN UP AREA.		220.00
	Kyle K	02.14.13 TEST UNIT FOR TRANS TEMP AND 4X4		200.00

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR
 UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET
 HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
 Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Bill Sto.	07.09.09 CHANGE OIL IN PLAETARIES IN FRONT. CRIB THE BACK TO JACK IT UP.		80.00
	Paul Riche	01.13.11 GET UNIT RUNNING AND BRING INTO SHOP		100.00
	Rick P.	12.16.11 REASSEMBLE HOOD AND EXHAUST,REPAIR THROTTLE BRACKET		280.00
	Carl	03.26.10 TOP UP HYDRAULIC OIL TANK. PREP REAR BOTTERY BOX FOR NEW SAFETY. HASP INSTALL. CHECKED ALL LIGHTS & ISNTRUMENTS. INSTALLED DECAL KIT.		140.00
	Gary M.	07.14.09 INSTALL LIMIT SWITCH FOR STABILIZERS. TIGHTEN LOOSE EXHAUST CLAMP. INSTALL FRONT LEFT TIRE AND TORQUE WHEEL NUTS. REINSTALL DUCTING BETWEEN ENGINE AIR FILTER AND TURBO. TOP UP ENGINE OIL. TOP UP TRANSMISSION. DRAIN COOLING SYSTEM. INSTALL INLINE BLOCK HEATER. FILL COOLING SYSTEM. INSTALL REAR ROD GROATING.		320.00
	Eric	03.24.11 CHANGED BOTH AIR ACTUATORS UNDERNEATH MACHINE. ONE FOR 2WD TO 4WD THE OTHER ONE WAS FOR LOWRANGE HIGHRANGE INSTALLED & TESTED. REPAIRED TAILLIGHTS & ADJUSTED HIRAIL SWITCH. MAKE SURE THERE WAS A NEW LOGBOOK & LOAD CHARTS IN HOLDER. CLEANED GARBAGE OUT OF CAB		160.00
	DERICK L.	03.24.11 START FAB ON SIDE COVERS ,CANCELLED UPON FINDING OLD SUMMER COVERS IN SNOW BANK		80.00
	Rick P.	03.31.10 WIRED IN POWER FOR AUXILLIARY POWER PLUG IN IN CAB. CHANGED DOOR HANDLE IN SIDE, BACK DOOR- HAD BEEN INSTALLED WRONG.		60.00
	Eric	12.16.11 REMOVED WIPER ARM LINKAGE-BROKEN.REPAIR WIRING UNDER DASH.HOOK UP THROTTLE,DISSASSEMBLED MASTER CYLINDER AND CLEANED REINSTALL MUFFLER AND HOOD		300.00

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X _____
Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Paul Riche	04.26.11 FIND AND INSTALL KNOB FOR FAN MOTOR, CHECK OVER THROTTLE PEDAL, BLEED OUT AIR FINISH INSTALLING AIR LINES, TEST AIR LINES WASH RAD, WASH MACHINE, ADJUST BRAKE.		280.00
	Phil St. J	07.14.09 REPAIR GUARD		40.00
	Carl	07.17.09 HELPED BARY WITH MOVING MACHINE. INSTALLING TOTE BOOM		80.00
	Gary M.	07.24.09 CHECK INTO WHY HI RAIL QUIT WORKING. FOUND LOOSE WIRE. FINISH PAINTING WINTER AND SUMMER SIDE COVERS.		80.00
	Gary M.	07.08.09 RE,PVE SIEZED LEVER PIN. PERFORM MACHINE SERVICE. MAKE NEW PIN FOR LEVER. CLEAN UP LEVER PIN HOLES. REMOVE BUSHING FROM LEVER AND LINK.		320.00
	Phil St. J	07.08.09 LANCE AND REMOVE PIN. FAB AND INSTALL ENGINE GUARDS (2 SETS)		320.00
	Bill Sto.	12.24.09 TARP, PUT A HEATER UNDER TO HEAT UP ENGINE. WOULD NOT START. REMOVE DRIVE SHAFTS AND E-BRAKE SO IT WILL FREE WHEEL		240.00
	Carl	04.15.10 MOUNT CYLINDER		60.00
	Eric	07.12.11 CLEAN VALVE COVER AND BREATHER.DISSASSEMBLE HYRAIL TO INSULATE HYRAIL GEAR,REINSTALL		120.00
	Rick P.	07.16.09 REPAIRS		80.00
	Rick P.	07.07.09 TOOK BOOM APART, CHECKED FOR DEFECTS		80.00
	Gary M.	07.07.09 REMOVE TOTE BOOM. STEAM CLEAN MACHINE. CONTINUE WITH INSPCTION.		320.00
	Phil St. J	07.07.09 CUT & DRILL NEW LIFT LUG PLATES TO REPLACE OLD TO PETTIBONE BOOM.		240.00

***** Thank You *****
Service Recommendations
ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Carl	07.07.09 REPLACED BROKEN CONVEX MIRROR. REPLACED BULB BRAKE/TURN RIGHT REAR. REPLACED BACK UP ALARM. HELP GARY WASH UNIT, REMOVE COVERS. MAKE PARTS LIST. FOLLOWED INSPECTION LIST. CUT 2 PINS FOR MACHINING.		160.00
	Eric	07.14.09 HELPED GARY PLUM AND INSTALL BLOCK HEATER		60.00
	Eric	03.01.11 TOPPED UP TRANSMISSION, CHANGED ALL 4 STEER CYLINDER BUSHINGS. REINSTALLED TIRES ON BACK OF UNIT. FINISHED CLEANING UP EMERGENCY BRAKE PARTS, NEED NEW SET OF PARK BRAKE SHOES		120.00
	Kyle K	01.30.13 THROTTLE CONTROLS		100.00
	Phil St. J	04.06.10 FAB FUEL TANK MOUNTING BRACKET		140.00
	DERICK L.	03.23.11 DRAFT UP[SIDE ENGINE PANELS		40.00
	DERICK L.	04.25.11 FABRICATE BOX AND MOUNT FOR PINDAL HOOK ON FRONT OF SPEEDSWING, FA AIR LINE & MOUNT FOR AIR SUPPLY PRIME & PAINT		260.00
	Rick P.	12.30.09 DRILLED AND CUT HOOK BOLT FOR BOOM, PUT ENGINE HOOD BACK ON. HELPED WITH ELECTRICAL		80.00
	Eric	12.30.09 REINSTALLED HOOD AND EXHAUST. REINSTALLED PARK BRAKE AND TESTED OPERATION. OK. FIXED & REPAIRED DASH ELECTRICAL HAD MOST FUNCTIONS HOOKED TO DIRECT POWER NOT SWITCHED SOURCE. REPAIRED GAUGES THAT WERENT WORKING. PUT UNIT OUTSIDE TO SEE IF IT WILL START COLD NEXT DAY		160.00
	Eric	03.27.12 CHECK STEERING FUNCTIONS AND CHECK FOR PROPER LABELLING		40.00
	Eric	04.07.10 CLEANED & PAINTED FUEL TANK FOR CAB HEATER, INSTALLED ON BRACKETS. CHANGED BREATHER CAP ON TOP OF FUEL TANK. PAINTED GREEN MARKING ON MAIN FUEL TANK. PAINTED TOP OF HYDRAULIC TANK BLUE.		80.00

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25
FRONT AND 1600R25 REAR
UNIT WEIGHTS 18520 KG OR 40830 LBS WITH
GENERATOR NO MAGNET
HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Kyle K	08.15.12 ROUTE AND INSTALL HYDRAULIC LINES AND VALVES FOR WINCH		360.00
	Eric	08.22.12 COMPLETE RENTAL CHECKLIST AND REPLACE STROBE LIGHT,LOAD UNIT ON FLOAT		160.00
	Kyle K	11.18.13-LABOUR-KYLE-REG 2 H0 Replaced back up alarm. Put grill back on. Tested machine ran boom to checked for leaks.		100.00
	Gary M.	07.09.09 INSTALL BUSHING IN LINK. CLEAN AIR COMPRESSOR FILTER AND INSTALL. CHANGE ENGINE MOUNTING BOLTS. TIGHTEN TRANSMISSION END PLATE BOLTS. REPLACE ALL FOUR LOWER TRANSMISSION BOLT AND NUTS. CHANGE HYDRAULIC TANK BREATHER		120.00
	Gary M.	07.15.09 INSTALL SEAT SWITCH FOR HYDRAULIC CUT OUT. ADJUST RIGHT FRONT CYLINDER ROD (HI RAIL). REPAIR PARK BRAKE LIGHT. MAKE REPAIRS TO SWING LOCK. ADJUST REAR LIMIT SWITCH FOR BACK UP ALARM. REMOVE FRONT TIE ROD. GET TIRES LINED UP. WORK ON TIE ROD ADJUSTMENT		320.00
	Bill Sto.	04.08.10 PUT DECALS ON. NEW ROOF LINER ON ONE SIDE. LOAD FOR SHIPPING		160.00
	Rick P.	04.01.10 CHANGED ENGINE OIL & FILTER, FUEL FILTER		80.00
	Phil St. J	04.07.10 FAB & INSTALL FUEL TANK BRACKETS AND PAINT		120.00
	Carl	04.07.10 BOOST UNIT OUTSIDE TO START ENGINE. INSTALLED SECOND BATTERY AND CABLES. REVERSE MASTER SWITCH CONNECTION TO GROUND CONTACT		80.00
	Greg B	07.27.09 PUT BOLT IN SPEEDSWING JIB		40.00
	Marc L	04.16.10 REPAIRS TO 360. INSTALL FRONT & REAR AIRLINES. INSTALL NEW MOTOR MOUNT BOLTS ON MAGNET ENGINE. BLEED BRAKES. REPAIR FUEL LEAK ON PUP ENGINE.		340.00

***** Thank You *****

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25
FRONT AND 1600R25 REAR
UNIT WEIGHTS 18520 KG OR 40830 LBS WITH
GENERATOR NO MAGNET
HRS JAN 24/2012 2398.3

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
Received By

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Bill Sto.	04.16.10 USE BOOM TRUCK TO BRING INTO SHOP FOR REPAIR NEW AIR COUPLER. WAIT FOR GREG TO GET BACK AND LOAD 360 SPEED SWING		440.00
	Kyle K	11.14.11 CHECK ALL FLUID LEVELS		60.00
	Rick P.	04.16.10 MOUNT HITCH AND HOSES		200.00
	Carl	07.09.09 REMOVED SEAT PADS AND ARM RESTS FOR UPHOLSTRY. WIPER MOTOR FRONT PIN BROKEN. REMOVED DISSASSEMBLED. REWELD PIN AND REINSTALLED. CAB CIRCULATION FOR SWITCH IS BROKEN, REMOVED AND REPLACED. HEAT FAN CONTROL KNOB MISSING REPLACED TIE UP AND SECURED LOOSE WIRING FRONT DRIVE HEAD LAMPS. REMOVED LF WHEEL TO GET AT BROKEN WHEEL STUD. CUT PLATE FOR NEW TRANS FILTER HOUSING.		280.00
	Kyle K	02.13.13 CHECK TRANSMISSION TEMPERATURE AND REPLACE SENDING UNIT,RUN AND TEST		300.00
	Nick C	08.17.12 HOSE AND WINCH INSTALLATION		100.00
	Kyle K	12.07.12 INSPECTION		80.00
	Eric	07.25.11 SERVICE		200.00
	Larry T.	05.03.13-LABOUR-LARRY-REG 56 H- Replace hyd hose from throttle master cylinder. bleed entire ignition		250.00
	DERICK L.	12.08.11 FABRICATE BRACKETS AND REALIGN AIR BOX		120.00
	Richard L	12.10.11 PRESSURE WASH UNIT		160.00
	Rick P.	12.13.11 REPLACE FUEL FILTERS,ASSIST WAJAX MECHANIC		60.00
	Rick P.	04.01.10 ADJUSTED IDLE & STOP, TOOK TOP MUFFLER OFF,PUT RAIN CAP ON. AIR COND. NOT WORKING, REWIRED IN POWER WITH IN LINE FUSE.		80.00
	Paul Riche	04.25.11 MAKE UP HOSES AND T INTO BRAKE SYSTEM		200.00
	Kyle K	08.16.12 PLUMB WINCH AND TEST PRESSURES		200.00

<p>***** Thank You *****</p>	<p>We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***</p>	<table border="1"> <tr> <td>Labor</td> <td>23,310.00</td> </tr> <tr> <td>Parts</td> <td>17,326.19</td> </tr> <tr> <td>Inspection</td> <td>0.00</td> </tr> <tr> <td>Towing</td> <td>0.00</td> </tr> <tr> <td>Sublet</td> <td>7,996.92</td> </tr> <tr> <td>Shop Charge</td> <td>0.00</td> </tr> <tr> <td>Subtotal</td> <td>48,633.11</td> </tr> <tr> <td>H.S.T.</td> <td>0.00</td> </tr> <tr> <td>Amount Paid</td> <td>0.00</td> </tr> <tr> <td>Total Due</td> <td>48,633.11</td> </tr> </table>	Labor	23,310.00	Parts	17,326.19	Inspection	0.00	Towing	0.00	Sublet	7,996.92	Shop Charge	0.00	Subtotal	48,633.11	H.S.T.	0.00	Amount Paid	0.00	Total Due	48,633.11
	Labor	23,310.00																				
Parts	17,326.19																					
Inspection	0.00																					
Towing	0.00																					
Sublet	7,996.92																					
Shop Charge	0.00																					
Subtotal	48,633.11																					
H.S.T.	0.00																					
Amount Paid	0.00																					
Total Due	48,633.11																					
<p>Service Recommendations</p> <p>ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3</p>	<p>I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.</p> <p>X _____ Received By</p>																					

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Carl	04.08.10 PRE RENTAL CHECK SHEET COMPLETED. PARKING BRAKE AND ALTERNATOR CHARGING LIGHT STAYING ON WHEN KEY OFF. REPAIRED IGNITION FEED WIRE LIVE BATTERY & MOVED TO IGNITION SWITCH BATTERY TERMINAL CONNECTION. TRANS PSI GAUGE NEEDLE PEG TO MAX. TROUBLESHOOT WIRES CROSSED ON PRESSURE SENDER-REPAIRED. REPLACED WIPER BLADES. INSTALLED DECALS-FIRE EXTINGUISHER & FIRST AID INSTALLED.		180.00
	Phil St. J	07.13.09 MODIFY SCREEN GUARDS (ENGINE)		120.00
	Carl	07.13.09 INSTALLED RE UPHULSTERED SEAT SET		20.00
	Eric	08.02.12 MOUNT WINCH AND REPAIR LIGHTS		220.00
	Kyle K	11.04.13-LABOUR-KYLE-REG 7 H-Removed hi rail pivot pin. Removed hi rail wheel front left. Removed bearing from hub and replaced. Drilled and tapped grease fitting. Reassembled front hi rail.		350.00
	Larry T.	11.01.13-LABOUR-LARRY-REG 6 H-Grease entire unit. Torqued wheels. Checked diff and plantary levels.		300.00
	Eric	07.17.09 HELPED GARY FINISH UP SPEEDSWING. PRIMED & PAINTED SIDE COVERS. MAKE A NEW BATTERY HOLD DOWN. REINSTALLED TOTE BOOM. INSTALLED NEW SENDING UNIT.		280.00
	Gary M.	07.17.09 WORKED ON DRIVE OIL PRESSURE GAUGE PROBLEM. INSTALL NEW GAUGE. NEED PROPER SENDING UNIT. VACUUM OUT CAB. INSTALL COVER OVER PUMPS AND DRIVELINE. INSTALL TOTE BOOM. CUT AND DRILL BOLT FOR BOOM TIP. FIX GREASE POINT.		300.00

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR
 UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET
 HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X _____
 Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin# : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Gary M.	07.20.09 REMOVE AIR BOX COVER. MAKE UP NEW GASKET, INSTALL COVER. INSTALL REAR DOOR HANDLE. INSTALL FIRST AID KIT. ADD FUEL CONDITIONER TO FUEL TANK. FUEL UP MACHINE. TIE UP HYDRAULIC HOSES. REMOVE REAR WINDOW LOCKING TABS AND INSTALL ON OPERATORS WINDOW.		240.00
	Rick P.	08.04.09 CHANGED TRANSMISSION PRESSURE GAUGE, WIRED IN NEW ENDS GAUGE READS 250PSI. GREASED BOOM PINS.		100.00
	Eric	07.07.11 MAKE GASKETS FOR BRAKE ASSY (SWING MOTOR)ADD OIL TO PLANETARY DRIVES-INSTALL NEW SEAL IN PUMP-TOP UP FRONT DIFF REPLACE U-JOINT FRONT DRIVESHAFT-REMOVE PARK BRAKE ASSEMBLY AND REPLACE BROKEN SPRING		180.00
	Eric	07.08.11 REINSTALL SWING BRAKE ASSEMBLY,REINSTALL HYDRAULIC HOSES		60.00
	Kyle K	04.30.12 DRAINED PLANETARIES TO LOWER LEVEL,CHECK FOR LEAKS-RESEAL COVERS,REPLACE COMPRESSOR OIL LINE,PRESSURE WASH MACHINE AND TEST		240.00
	Rick P.	12.14.11 ENGINE		40.00
	Nick C	06.05.12 REPLACE LEFT FRONT TIRE WITH SPARE AND TORQUE TO SPEC,REPLACE LEFT REAR HYRAIL CYLINDER HOSE		60.00
	Nick C	05.02.13-LABOUR-NICK- REG 1 H- Tested fuel system for pressure leak		50.00
	Larry T.	05.02.13-LABOUR-LARRY-REG 2 H-Troubleshoot Throttle		100.00
	Kyle K	06.06.12 INSTALL LEVEL INDICATOR TEST AND REPAIR INDICATOR LIGHTS		120.00

***** Thank You *****	We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***	Labor	23,310.00		
		Parts	17,326.19		
Service Recommendations ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3	I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.	Inspection	0.00		
		Towing	0.00		
		Sublet	7,996.92		
		Shop Charge	0.00		
		Subtotal	48,633.11		
		H.S.T.	0.00		
		Amount Paid	0.00		
		Total Due	48,633.11		
		X _____	Received By		

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Paul Riche	04.27.11 MOUNT FIRE EXTINGUISHER AND HEATER HOSE BRACKET, GO OVER UNIT, FILL FUEL TANK, FILL COOLANT, FIX FAN FOR AIR CONDITIONING, LABEL DASH, CHECK ALL LIGHTS, HORNS & ALARMS, CHECK ALL GAUGES, TEST ALL FUNCTIONS		260.00
	Derek L.	11.14.13-LABOUR-D LAPORTE-O.T. 0.5 H-Re and Re and replace seals on lift cylinders.		25.00
	Kyle K	03.27.12 INSTALL OSCILLATION CYLINDER,REPAIR RADIO WIRING		240.00
	DERICK L.	TORQUE WHEELS AND CLEAN CAB		120.00
	Gary M.	08.14.12 CLEAN UNIT AND PAINT AREAS		80.00
	Derek L.	10.23.09 FINISH PAPERWORK, CLEAN OUT TRUCK.		400.00
	Bill Sto.	11.14.13-LABOUR-D LAPORTE-REG 8 H-Re and Re and replace seals on lift cylinders.		20.00
	Carl	03.26.10 CHANGE FITTING ON MAIN TIP		320.00
	Phil St. J	07.08.09 DRAINED FRONT AND REAR DIFF AND REFILLED. DRAINED FRONT AND REAR SWING MOTOR, REPLACED HYDRAULIC FILTER. DRAINED TRANSMISSION. CLEARED REINSTALLED STRAINER. LUBED ALL GREASE FITTINGS. INSTALLED DRAIN VALVE ON TANK WITH QUICK COUPLER. H STYLE. ASSIST GARY WITH REPAIRS.		160.00
	Gary M.	07.17.09 FAB & INSTALL NEW SAFETY CHAIN HOOK. REPAIR FRONT HI RAIL SWIVEL PIN. INSTALL NEW BOOM PIN		220.00
	Phil St. J	07.21.09 LOCK REAR WINDOW WITH OLD LOCKING TABS. PUT PROTECTIVE COVERING OVER WIRING INTO CENTER POST SLIP RING. MODIFY COVER TO PREVENT CENTER POST COVER. WORK ON TORQUE CONVERTER GAUGE PROBLEM. TIGHTEN HYDRAULIC ADAPTER FITTING FOR AIR CONDITIONING HOISING		120.00
		07.10.09 WELD FILTER HOUSING TO REAR. INSTALL DOOR STOPS.		

***** Thank You *****
Service Recommendations
ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***
I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.
X _____ Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1		Vin # : 3045	Motor Hours : 2782.4
Phone2	Ext.	Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Eric	07.11.11 TOP UP LEVELS ON SWINFG GEAR PLANETARIES,INSTALL FRONT DRIVESHAFT,REINSTALL PARK BRAKE LINKAGE AND ADJUST,REPAIR BROKEN WIRES FOR S-BAR HEATER AND TEST REMOVE VALVE COVER		260.00
	Eric	12.29.09 REMOVED HOOD FOR HARPER TO BE ABLE TO DO A COMPRESSION TEST. REINSTALLED FRONT AND REAR DRIVE SHAFTS		40.00
	Eric	07.05.11 REASSEMBLE HIGH LOW SELECTOR,ADJUST AIR ACTUATOR,REINSTALL DRIVESHAFT AND YOKES, TOP UP DIFF FLUIDS,REMOVE AND DISSASSEMBLE SWING GEAR ASSY.DISSASSEMBLE BRAKE ASSY AND CHECK FOR WEAR		300.00
	DERICK L.	07.06.11 ASSIST WITH REPAIRS		60.00
	Eric	07.06.11 REMOVE FRONT PLANETARY AND REPLACE SEAL		180.00
	Gary M.	07.10.09 START ON AIR DRIER INSTALLATION		80.00
	Gary M.	07.16.09 REMOVE FRONT END REAR WHEEL TIE RODS. FREE UP SIEZED ROD ENDS. ADJUST AND REINSTALL WHEEL TIE RODS. GREASE TORQUE CONVERTER DRIVE SHAFT. FILL SWING MOTOR. CLEAN SWING MOTOR BREATHER CAPS. MAKE TAG FOR BLOCK HEATER. REPAIR TRANSMISSION GAUGE. CHECK TO SEE WHY DRIVE OIL GAUGE IS NOT WORKING. INSTALL GAUGE AND SENDING UNIT.		320.00
	Gary M.	07.06.09 MOVE BUCKET AND FORKS INTO YARD. START TO CHECK MACHINE OVER		80.00
	Eric	08.19.09 REPAIR BROKEN WIRE FOR HYD LOCK ARM		40.00
	Kyle K	02.12.13 REPAIR OIL LEAKS,ADJUST BACK UP SWITCH-LOCATE AND REPAIR WIRING FOR CAB GAUGES		400.00

***** Thank You *****	We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***	Labor	23,310.00
		Parts	17,326.19
Service Recommendations ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3	I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.	Inspection	0.00
		Towing	0.00
		Sublet	7,996.92
		Shop Charge	0.00
		Subtotal	48,633.11
		H.S.T.	0.00
		Amount Paid	0.00
	X _____ Received By	Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Eric	07.04.11 DISCONNECT AIR SHIFTERS FROM TRANS AND TEST		300.00
	Eric	REMOVE HI-LO SELECTOR SHAFT ASSY FROM TRANS-REPLACE SHAFT AND DETENT SPRING ASSY-REMOVE FRONT WHEEL DRIVE ACTUATORS TEST AND CLEAN-DRAIN TRANS FLUID		300.00
	Eric	07.22.11 TROUBLE SHOOT ELECTRICAL FOR TRANSMISSION		40.00
	Eric	06.30.11 check unit		160.00
	Eric	07.13.11 INSTALL VALVE COVER-COMPLETE ASSEMBLY,RUN AND TEST		350.00
	DERICK L.	11.04.13-LABOUR-DERICK-REG 7 H-Change out pivot shaft on front hyrails. Assist Kyle on repairs.		60.00
	Nick C	08.16.12 TOUCH UP PAINTED AREAS		380.00
	Kyle K	08.17.12 INSTALL DIVERTER VALVES AND TEST WINCHES		320.00
	Kyle K	08.20.12 Install diverter valve and 1" hydraulic lines		360.00
	Nick C	08.21.12 MOUNT WINCH AND TEST-REPLACE WIRE ROPE WITH 5/8X150'		120.00
	Nick C	08.21.12 POWER WASH UNIT AND PAINT REQUIRED AREAS		80.00
	Nick C	08.22.12 PRESSURE WASH UNIT,CHECK TIRE PRESSURES AND OREP FOR RENTAL		300.00
	Kyle K	01.31.13 CHECK THROTTLE OPERATION		160.00
	Derek L.	01.30.13 BRING UNIT INTO SHOP AND CHECK THROTTLE INSTALLATION		80.00
	Nick C	01.30.13 RETREIVE SPARE TIRE,CHECK THROTTLE OPERATION		200.00
	Nick C	01.31.12 SERVICE UNIT (2720HRS) ATTEMPT TO RUN NEW THROTTLE LINES-BLEED THROTTLE LINE,CHECK ALL LIFGHTS		80.00
	Nick C	02.01.13 ALIGN FRONT END AND GEASE TIE RODS		

***** Thank You *****

Service Recommendations

ENGINE SER# 4D-229359 TIRE SIZE 1600-25
 FRONT AND 1600R25 REAR
 UNIT WEIGHTS 18520 KG OR 40830 LBS WITH
 GENERATOR NO MAGNET
 HRS JAN 24/2012 2398.3

We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X _____
 Received By

Labor	23,310.00
Parts	17,326.19
Inspection	0.00
Towing	0.00
Sublet	7,996.92
Shop Charge	0.00
Subtotal	48,633.11
H.S.T.	0.00
Amount Paid	0.00
Total Due	48,633.11

PO # 20298

Invoice Date: 01/10/2014

Invoice # 20298

Phone1	Ext.	Vin # : 3045	Motor Hours : 2782.4
Phone2		Yr/Make : 1993 Pettibone 360 Speedswing	Writer : Marc L
		Model : 360 Speedswing	Date : 06/23/2009
		Plate :	Motor :
		Miles :	Unit # : 20298

Quantity	Part Number / Tech	Description	Parts	Labor
	Eric	02.07.13 SRTART UNIT AND BRING INTO SHOP-REPAIR WIRING,BLEED THROTTLE AND TEST-FLUID BLEEDS DOWN WHEN SITTING		400.00
	Eric	02.11.13 REPAIRS		25.00
	Nick C	11.18.13-LABOUR-NICK-REG 4 H- Brought unit in. Removed throttle master cylinder and replaced seals. Reinstalled, bleed and tested throttle. Replaced hook on boom and on winch. Cut tab off front hi rail axle, cleaned primed and painted. Cleaned cab and tools. Topped hydraulic oil.		200.00
	DERICK L.	11.05.13-LABOUR-DERICK-REG 2 H- Assist Kyle on rear hyrail.		100.00
	Kyle K	11.05.13-LABOUR-KYLE-REG 6 H-Replace bearings in left rear hub. Greased new bearings. Installed hub on machine. Installed pineapple on hub. fixed wiring on left arm rest. Cleaned up wiring on cab. Back up beeper not working. Hyrail switch was unadjusted, fixed it up.		300.00
	Nick C	11.14.13-LABOUR-NICK-REG 5 H- Remove both main lift cylinders. Dissembled. Reassembled lift cylinder installed. Cleaned pins. Tested unit. Repaired leak in check valve.		250.00
	Sublet	REPAIR ENGINE CHANGE INJECTORS		2,395.94
	Sublet	BROKERAGE CHARGE TO CLEAR RIG. JULY 7 09 INVOICE#		150.00
	Sublet	RE-UPHOLSTER CUSHION SEAT & BACK INVOICE# 68572		165.00
	Sublet	MANUFACTURE 3 LEVER BUSHINGS. JULY 23 09, INVOICE#		460.98
	Sublet	2 PINS JULY 23 09, INVOICE # 91855		208.00
	Sublet	Float Speedswing from Sleepy Eye,MN to Sudbury and unload		4,300.00
	Sublet	INSTALL TIRE		252.00
	Sublet	INV# 00550652 - BROKERAGE FEE FOR PARTS PETTIBONE		32.50
	Sublet	INV#00550648 - BROKERAGE FEE PARTS FROM PETTIBONI		32.50

***** Thank You *****	We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***	Labor	23,310.00		
		Parts	17,326.19		
Service Recommendations ENGINE SER# 4D-229359 TIRE SIZE 1600-25 FRONT AND 1600R25 REAR UNIT WEIGHTS 18520 KG OR 40830 LBS WITH GENERATOR NO MAGNET HRS JAN 24/2012 2398.3	I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.	Inspection	0.00		
		Towing	0.00		
		Sublet	7,996.92		
		Shop Charge	0.00		
		Subtotal	48,633.11		
		H.S.T.	0.00		
		Amount Paid	0.00		
		Total Due	48,633.11		
		X _____	Received By		