

PO #

Invoice Date: 02/22/2013

Invoice #

26660

Vin # : 2864  
 Yr/Make : 1986 Pettibone SPEEDSWING  
 Model : 360 Speedswing  
 Plate :  
 Miles :

Motor Hours : 2291  
 Writer : Marc L  
 Date : 12/02/2011  
 Motor :  
 Unit # : 26660

Ext.

Quantity	Part Number / Tech	Description	Parts	Labor
1.00	599	CHAMPION HTR PLUG	12.47	
1.00	G25165-0808	FITTING	7.99	
1.00	G25170-0808	FITTING 8G8FJX	6.77	
3.00	6G2	HOSE #6	7.14	
1.00	8G2	HOSE #8	3.24	
1.00	P550132	FILTER ENGINE OIL C	7.30	
1.00	DS198	HEADLIGHT SWITCH	37.17	
16.00	dextron111	TRANS FLUID	44.00	
25.00	80W90	GEAR LUBE	87.50	
1.00	4D-XHD	BATTERY 12V 4D	182.95	
1.00	95534	KEY SWITCH	77.23	
1.00	51970	SUB FROM CAR Q 85970	0.00	
1.00	27034INV	SUPPLY&INSTALL GLASS	181.45	
1.00	P555570	LUBE SPIN ON	4.45	
3.00	G25179-0606	FITTING 90' FEMALE	35.10	
3.00	G25170-0606	6G-6FJX FITTING	14.55	
1.00	00357477INV	BROKERAGE FEES	91.00	
1.00	OLA-00383-006	Master Cylinder (brake)	702.23	
2.00	CWR40 N	STEEL WHEELS CWR 40 NEW	5,064.80	
2.00	CN1017106	HY RAIL QUARD LEFT SIDE	399.96	
2.00	CN1017108	HY RAIL GUARD RIGHT SIDE	399.96	
16.00	0L1-07802-00	BUSHING HY RAIL INSULATOR	171.52	
2.00	0L1-3975-2	STEEL RING ,445,441,360	385.06	
3.00	5582	SWITCH -TOGGLE	19.62	
1.00	44810	FLASHER 2 PRONG HD12	6.48	
1.00	77103	MINI STROBE AMBER	66.50	
1.00	097-018	HOOD LATCH	32.58	
2.00	G25170-1212	12G-12FJX	21.28	
20.00	12G2	HOSE #12	127.00	
2.00	15366	VBELT WATER PUMP	18.90	
2.00	17411	VBELT - FAN	27.14	
1.00	2484-16	MASTER DISCONNECT SWITCH	30.17	

\*\*\*\*\* Thank You \*\*\*\*\*

We Believe that quality workmanship, will protect your Investment and your family.\*\*\*Thank You for your Business and Come Again!\*\*\*

Labor	9,200.00
Parts	11,391.26
Inspection	0.00
Towing	0.00
Sublet	11,390.00
Shop Charge	0.00
Subtotal	31,981.26
H.S.T.	0.00
Amount Paid	0.00
<b>Total Due</b>	<b>31,981.26</b>

**Service Recommendations**

TIRE SIZE 1600-25 BIAS PLY

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X \_\_\_\_\_  
 Received By

PO #

Invoice Date: 02/22/2013

Invoice #

26660

	Vin # : 2864 Yr/Make : 1986 Pettibone SPEEDSWING Model : 360 Speedswing Plate : Miles :	Motor Hours : 2291 Writer : Marc L Date : 12/02/2011 Motor : Unit # : 26660
Ext.		

Quantity	Part Number / Tech	Description	Parts	Labor
2.00	53052	LAMP PEDESTAL 2 WIRE BLACK	33.26	
12.00	15W40	15W40 MOTOR OIL	30.72	
1.00	55014	switch toggle 2 blade	4.40	
1.00	PL-19-RL	CH PILOT LIGHT	5.00	
2.00	G25179-0606	FITTING 90' FEMALE	23.40	
2.00	G25170-0606	6G-6FJX FITTING	10.18	
4.00	6G2	HOSE #6	9.52	
3.00	KL527	HD BRAKE FLUID 24/CSE	9.63	
4.00	CN1017107	MOUNTING PLATE	194.00	
1.00	76074-60	DUAL PRESSURE SWITCH	26.38	
5.00	80W90	GEAR LUBE	17.50	
1.00	P165314	HYD TANK FILTER 441B CANISTER	32.56	
1.00	4D-XHD	BATTERY 12V 4D	182.95	
2.00	G25170-0404	FITTING 4G- 4FJX	9.48	
5.00	4G2	HOSE #4 HYD 2 WIRE	9.50	
2.00	G25170-0606	6G-6FJX FITTING	10.18	
4.00	6G2	HOSE #6	9.52	
2.00	G25170-0808	FITTING 8G8FJX	13.54	
4.00	2556-20	LOW PRESS HOSE	24.24	
15.00	8G2	HOSE #8	48.60	
1.00	G60424-0808	ADAPTOR 8MJ-8FJX45	3.07	
2.00	P562261	HEAD ASSY (SPIN ON FUEL)	32.60	
1.00	P558000	FILTER, FUEL	10.19	
1.00	P550105	FUEL FILTER	4.85	
1.00	KNBE13250	SWITCH-STOPLITE	30.51	
2.00	15370	ALTERNATOR BELT (REF ONLY)	0.00	
1.00	702X5	FLARE UNION	12.75	
3.00	101C	ANTIFREEZE - GREEN	38.04	
2.00	53216	RAD HOSE	40.88	
4.00	0L1-07651-000	INSULATING DISC	523.76	
1.00	100828INV	10' OF 1" ANGLE IRON	20.00	
1.00	61091-5	Grote Dome Light	20.09	

\*\*\*\*\* Thank You \*\*\*\*\*

We Believe that quality workmanship, will protect your Investment and your family.\*\*\*Thank You for your Business and Come Again!\*\*\*

Labor	9,200.00
Parts	11,391.26
Inspection	0.00
Towing	0.00
Sublet	11,390.00
Shop Charge	0.00
Subtotal	31,981.26
H.S.T.	0.00
Amount Paid	0.00
<b>Total Due</b>	<b>31,981.26</b>

**Service Recommendations**

TIRE SIZE 1600-25 BIAS PLY

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not responsible for any loss or damage to vehicle.

X \_\_\_\_\_  
Received By

PO #

Invoice Date: 02/22/2013

Invoice #

26660

	Vin # : 2864 Yr/Make : 1986 Pettibone SPEEDSWING Model : 360 Speedswing Plate : Miles :	Motor Hours : 2291 Writer : Marc L Date : 12/02/2011 Motor : Unit # : 26660
Ext.		

Quantity	Part Number / Tech	Description	Parts	Labor
6.00	533908	YELLOW PAINT	38.52	
4.00	G60301-0810	ADAPT	5.88	
4.00	G60312-0808	ADAPTOR 8MB-8MJ90	9.92	
2.00	G25179-0808	8G-8FJX90S	29.88	
1.00	00403369inv	BROKERAGE-PETTIBONE	32.50	
22.00	G25170-0808	FITTING 8G8FJX	148.94	
8.00	G25170-0606	6G-6FJX FITTING	40.72	
4.00	8G2	HOSE #8	12.96	
30.00	6G2	HOSE #6	71.40	
1.00	ESPAR	D2 AIR HTR s/n 867941BA	899.95	
4.00	65012	1 INCH HEATER HOSES	6.84	
1.00	281923X	DRAIN VALVE	49.95	
1.00	FA-VB-5	BRACKET	31.99	
1.00	5947INV	REPACK CYLINDER	297.00	
	Kyle K	08.15.12 SET UP UNIT FOR WELDING		40.00
	Nick C	08.10.12 REPLACE DAMAGED FITTINGS AND GREASE UNIT		60.00
	Harold F	08.10.12 SPEEDSWING INSPECTION		100.00
	Richard L	05.28.12 ASSIST WITH VALVE INSTALATION		160.00
	Kyle K	05.28.12 INSTALL HYDRAULIC LOCK VALVES-MAKE UP HOSES		320.00
	Kyle K	05.29.12 REROUTE HOSES FOR HYRAIL LOCKS AND TEST		240.00
	Kyle K	03.29.12 TROUBLE SHOOT LIGHTS,INSTALL STROBE,INSTALL NEW SWITCHES		160.00
	Kyle K	05.10.12 TROUBLESHOT CAB HEATER		320.00
	Eric	12.02.11 REMOVE HORNETS NEST AND REPAIR WIRING TO IGNITION SWITCH,CHECK MACHINE.FRONT BRAKES LEAKING		140.00
	Rick P.	12.02.11 BOOST START UNIT,REPLACE 1 BATTERY.CHECK MASTER SWITCH AND REPLACE KEY SWITCH		160.00
	Richard L	12.02.11 ASSIST MECHANICS		40.00
	Kyle K	05.22.12 INSTALL ESPAR HEATER		320.00

\*\*\*\*\* Thank You \*\*\*\*\*

We Believe that quality workmanship, will protect your Investment and your family.\*\*\*Thank You for your Business and Come Again!\*\*\*

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X \_\_\_\_\_  
Received By

Labor	9,200.00
Parts	11,391.26
Inspection	0.00
Towing	0.00
Sublet	11,390.00
Shop Charge	0.00
Subtotal	31,981.26
H.S.T.	0.00
Amount Paid	0.00
<b>Total Due</b>	<b>31,981.26</b>

**Service Recommendations**

TIRE SIZE 1600-25 BIAS PLY

PO #

Invoice Date: 02/22/2013

Invoice # 26660

Ext.	Vin # : 2864	Motor Hours : 2291
	Yr/Make : 1986 Pettibone SPEEDSWING	Writer : Marc L
	Model : 360 Speedswing	Date : 12/02/2011
	Plate :	Motor :
	Miles :	Unit # : 26660

Quantity	Part Number / Tech	Description	Parts	Labor
	Kyle K	03.28.12 CHECK UNIT FOR REPAIRS AND LIST,WORK ON LIGHTS		320.00
	Kyle K	05.15.12 REPLACE DOME LIGHT,CHECK CENTRE POST FOR LEAKS,CLEANED STEERING SOLENOIDS,PRESSURE WASHED BOOM AND TIGHTEN CYLINDER END CAP		320.00
	Kyle K	04.30.12 REPLACE TWO ENGINE COVER LATCHES		40.00
	Richard L	04.19.12 INSTALL BOOM ON UNIT		120.00
	Richard L	03.28.12 ASSIST WITH INSPECTION		160.00
	Nick C	04.20.12 REMOVE 3 HYRAILS AND INSTALL ONE AND PINAPPLE		120.00
	Nick C	05.07.12 REPLACE MASTER CYLINDER AND BLEED BRAKES-REFILL RESERVOIR		60.00
	Eric	05.07.12 WORK ON UNIT		60.00
	Luc B.	05.09.12 CHECK LIGHTS AND WIRING,REPLACE MASTER SWITCH AND PRESSURE SWITCH		160.00
	Luc B.	05.03.12 PRESSURE WASH UNIT AND REPAIR ELECTRICAL CHANGE LIGHTS		160.00
	Kyle K	05.09.12 REPAIR BROKEN BOLTS AND RETAP HOLES-REINSTALL GRILLE		120.00
	Jamie C	04.19.12 SPEED SWING REPAIRS		280.00
	Luc B.	05.09.12 ADJUST FRONT BRAKES,AND REPLACE REAR WHEEL SWITCH AND INDICATOR LIGHT,CHECK IN CAB HEATER,REPLACE HYDRAULIC HOSE		360.00
	Nick C	05.07.12 PRESSURE WASH UNIT		20.00
	DERICK L.	04.24.12 CUT OUT HYRAIL GUARDS AND WELD IN NEW BOLTS ON PUCKS-PAINT		160.00
	Kyle K	05.09.12 CHECK HEATER OPERATION AND AND REPAIR,REPLACE BATTERY AND MAKE UP NEW CABLES,REPLACE AIR HOSE		320.00

\*\*\*\*\* Thank You \*\*\*\*\*

We Believe that quality workmanship, will protect your Investment and your family.\*\*\*Thank You for your Business and Come Again!\*\*\*

Labor	9,200.00
Parts	11,391.26
Inspection	0.00
Towing	0.00
Sublet	11,390.00
Shop Charge	0.00
Subtotal	31,981.26
H.S.T.	0.00
Amount Paid	0.00
<b>Total Due</b>	<b>31,981.26</b>

**Service Recommendations**

TIRE SIZE 1600-25 BIAS PLY

I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.

X \_\_\_\_\_  
Received By

PO #

Invoice Date: 02/22/2013

Invoice #

26660

	Vin # : 2864 Yr/Make : 1986 Pettibone SPEEDSWING Model : 360 Speedswing Plate : Miles :	Motor Hours : 2291 Writer : Marc L Date : 12/02/2011 Motor : Unit # : 26660
Ext.		

Quantity	Part Number / Tech	Description	Parts	Labor
	Kyle K	05.11.12 REPLACE HYDRAULIC HOSE AND TROUBLESHOOT CAB HEATER, CHECK AND TEST REAR STEER FUNCTION -TESTED COILS		300.00
	Nick C	04.19.12 WORK ON HYRAIL WHEELS		100.00
	Luc B.	04.20.12 REMOVE HOSES		40.00
	Kyle K	04.20.12 SERVICE UNIT,REPLACE TRANSMISSION AND DIFFERENTIAL FLUIDS,REPLACE ENGINE OIL AND FILTERS		240.00
	Kyle K	04.21.12 FABRICATE AND INSTALL SPIN ON FUEL FILTERS AND HOUSINGS,MAKE NEW LINES		200.00
	Marc L	04.20.12 REMOVE FRONT STEER CYLINDER AND REPAIR WIRING		100.00
	Marc L	04.23.12 REMOVE FRONT LIGHTS AND GUARDS,REWELD BRACKETS TO FIT LIGHTS PROPERLY		120.00
	Kyle K	04.23.12 ASSEMBLE RIGHT FRONT PLANETARY,REPLACE SWING MOTOR OIL,REPLACE TRANS FILTER, UNIT WOULD NOT START FAULTY MASTER SWITCH		320.00
	Nick C	04.23.12 REPLACE HYDRAULIC TANK FILTER		20.00
	Jamie C	04.24.12 INSTALL GUARDS		160.00
	Eric	04.23.12 INSTALL PLANETARY COVERS AND TORQUE WHEELS,CHECK WIRING FOR MASTER SWITCH TO STARTER CONNECTIONS,REQUIES NEW SWITCH		100.00
	Marc L	04.26.12 TROUBLESHOT ELECTRICAL		80.00
	Kyle K	04.25.12 CHECK PARK BRAKE OPERATION AND REPLACE AIR EXHAUST MUFFLER REPLACE LOWER RAD HOSE AND BELTS		200.00
	Kyle K	04.26.12 REPLACE LOWER RAD HOSE AND FILL WITH NEW ANTIFREEZE		240.00
	Marc L	04.26.12 ELECTRICAL TROUBLESHOOTING		80.00

<p>***** Thank You *****</p> <hr/> <p style="text-align: center;"><b>Service Recommendations</b></p> <p>TIRE SIZE 1600-25 BIAS PLY</p>	<p>We Believe that quality workmanship, will protect your Investment and your family.***Thank You for your Business and Come Again!***</p> <hr/> <p>I hereby authorize you to perform the above repair work including necessary parts and materials set forth. Additional labor, parts or materials may be required to repair the vehicle, and further such repairs shall not be performed until after I have authorized them either in writing or verbally. You and your employees are authorized to operate the vehicle on streets, highways or elsewhere at my risk for the purpose of test inspection and delivery. It is understood and agreed the repair facility is not respnsible for any loss or damage to vehicle.</p> <p style="text-align: center;">X _____ Received By</p>	<table border="1"> <tr> <td>Labor</td> <td style="text-align: right;">9,200.00</td> </tr> <tr> <td>Parts</td> <td style="text-align: right;">11,391.26</td> </tr> <tr> <td>Inspection</td> <td style="text-align: right;">0.00</td> </tr> <tr> <td>Towing</td> <td style="text-align: right;">0.00</td> </tr> <tr> <td>Sublet</td> <td style="text-align: right;">11,390.00</td> </tr> <tr> <td>Shop Charge</td> <td style="text-align: right;">0.00</td> </tr> <tr> <td>Subtotal</td> <td style="text-align: right;">31,981.26</td> </tr> <tr> <td>H.S.T.</td> <td style="text-align: right;">0.00</td> </tr> <tr> <td>Amount Paid</td> <td style="text-align: right;">0.00</td> </tr> <tr> <td><b>Total Due</b></td> <td style="text-align: right;"><b>31,981.26</b></td> </tr> </table>	Labor	9,200.00	Parts	11,391.26	Inspection	0.00	Towing	0.00	Sublet	11,390.00	Shop Charge	0.00	Subtotal	31,981.26	H.S.T.	0.00	Amount Paid	0.00	<b>Total Due</b>	<b>31,981.26</b>
Labor	9,200.00																					
Parts	11,391.26																					
Inspection	0.00																					
Towing	0.00																					
Sublet	11,390.00																					
Shop Charge	0.00																					
Subtotal	31,981.26																					
H.S.T.	0.00																					
Amount Paid	0.00																					
<b>Total Due</b>	<b>31,981.26</b>																					

