

Locomotiv	Defect	Defect	Defect	Defect	Defect	Defect
Class	Code	Type	Date	Logged By	Seq	Description
SD60	81	INSPECTION PAST DUE	12/22/10	SAN LUIS P	1	AN M06 INSPECTION WAS/IS SCHEDULED ON 12/22/2010 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	170	ELECTRICAL-NO LOAD	10/29/10	G. VIVEROS	1	NON-WORKING MONITORS
SD60	220	ENGINE SUPPORT (FUEL/OIL/WATER LEAKS, ETC...)	12/1/10	PROVEEROF	1	NO TRABAJA MOTOR DIESEL (FALLA EN MOTORES DE ARRANQUE)
SD60	24.3	KCCD	8/30/08	SUPERVISO	1	INGRESA A INSPECCION DE PROGRAMA " T "
SD60	32.2	ELE PROBLEM NOT WORKING	10/13/08	CREW	1	WON'T CRANK
SD60	63	NEED WHEELS TRUED	11/9/08	INSPECTOR	1	WHEEL VARIATION. NEED TO TURN #1 WHEEL DOWN TO 26
SD60	82	SHOPPED EARLY FOR INSP	11/14/08	DR J	1	COMPLETE FEDERAL
SD60	32.1	ELE PROBLEM WORKING	11/15/08	RH	1	WINTERIZATION DUE
SD60	32.1	ELE PROBLEM WORKING	11/15/08	RH	2	WINTERIZATION DUE
SD60	12.1	BAD ORDER AIR CONDITIONING	11/21/08	KURT METZ	1	AIR CONDITION LEAKING WATER AROUND SEAL WHEN IT RAIN
SD60	BATT	BAD ORDER BATTERIES	12/12/08	B. MENA	1	NO ARRANCA MOTOR DIESEL POR TENER LAS BATERIAS DEBILES
SD60	16.1	DYING NOTHING TRIPPING	12/12/08	B. QUEZAD	1	OPERA PARO POR GOBERNADOR
SD60	102	DERAILMENT DAMAGE	12/20/08	A. AVALOS	1	DESCARRILADA DE AMBOS TRUCK'S
SD60	32.2	ELE PROBLEM NOT WORKING	1/23/09	D. PIÑA	1	NO TRABAJA MOTOR BOMBA DE COMBUSTIBLE
SD60	32.2	ELE PROBLEM NOT WORKING	1/24/09	L.A.DAVILA	1	SE DETIENE CONSTANTEMENTE MOTOR DIESEL
SD60	32.1	ELE PROBLEM WORKING	2/3/09	E. MOCTEZU	1	SE CORTA EL AMPERAJE EN POTENCIA
SD60	32	DYNAMIC BRAKES B/O	2/5/09	J. PEREZ	1	AL OPERAR EL FRENO DINAMICO OPERA PATINAMIENTO
SD60	32.2	ELE PROBLEM NOT WORKING	2/7/09	C.I.L DE SA	1	OPERA PATINAMIENTO DE RUEDAS EN POTENCIA Y FRENO DINAMICO
SD60	81	INSPECTION PAST DUE	3/2/09	SAN LUIS P	1	AN M03 INSPECTION WAS/IS SCHEDULED ON 03/03/2009 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	81	INSPECTION PAST DUE	5/31/09	SAN LUIS P	1	AN M06 INSPECTION WAS/IS SCHEDULED ON 06/01/2009 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	100	FUMES IN HOUSING/CASING	6/5/09	MAYORDO	1	ARROJA DEMASIADAS EMISIONES DE HUMO POR MULTIPLE DE ESCAPE
SD60	34	FRA WORKING TO SHOP	7/4/09	GE V DE M	1	FUGA DE AIRE EN TUBERIA DE LIMPIABRISAS POR INTERIOR DE PARED DE CABINA
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	9/1/10	MAYORTDC	1	FAN COOLING SYSTEM ORDER # 3 MAL
SD60	81	INSPECTION PAST DUE	9/28/10	SAN LUIS P	1	AN M12 INSPECTION WAS/IS SCHEDULED ON 09/28/2010 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	300	NO START	7/31/14	SILAO	1	NO ARRANCA MOTOR DIESEL
SD60	20	AIR-AIR COMPRESSOR	2/27/11	N. GARCIA	1	NO AIR COMPRESSOR FULL AIR PRESSURE (COMPRESOR DE AIRE NO COMPLETA LAS PRESIONES DE AIRE)
SD60	300	NO START	9/17/13	F GALLO	1	NO ARRANCA EL MOTOR DIESEL
SD60	350	TRUCK MISC.	3/11/11	G. VIVEROS	1	BO HANDBRAKE DOES NOT APPLY (FRENO DE MANO MAL ORDEN NO APLICA)
SD60	81	INSPECTION PAST DUE	3/24/11	SAN LUIS P	1	AN M03 INSPECTION WAS/IS SCHEDULED ON 03/24/2011 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	140	ELECTRICAL-GROUND RELAY (TCC C/O NO HELP)	5/24/11	CREW	1	AT 1350HRS CREW REPORTED UNIT WAS KGR. CREW TRIED TO RESET KGR AND ALSO TRIED TO CUT OUT MOTORS AND THEY ARE UNABLE TO GET GROUND RELAY TO F
SD60	81	INSPECTION PAST DUE	6/22/11	SAN LUIS P	1	AN M12 INSPECTION WAS/IS SCHEDULED ON 06/22/2011 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	180	ELECTRICAL-TCC OR TM CUT OUT	6/29/11	M. ZARAGO	1	RELAY GROUND OPERA "GR" IN POWER IS VOID MOTOR DRIVE # 6 (OPERA RELEVADOR DE TIERRA "GR" EN POTENCIA SE ANULO MOTOR TRACCION # 6)
SD60	130	ELECTRICAL-DYNAMIC BRAKING	7/22/11	MALONSO	1	DYNAMIC BRAKE INOPERATIVE
SD60	81	INSPECTION PAST DUE	9/21/11	SAN LUIS P	1	AN M03 INSPECTION WAS/IS SCHEDULED ON 09/21/2011 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	220	ENGINE SUPPORT (FUEL/OIL/WATER LEAKS, ETC...)	10/2/11	F VIVEROS	1	WATER LEAK RADIADORES BANK
SD60	170	ELECTRICAL-NO LOAD	11/8/11	A RUGERIO	1	EARTH OPERA RELAY
SD60	30	CAB MISC	12/7/11	E. ESCALEN	1	FUGA DE RECIDUOS DEL DEPOSITO DEL SANITARIO
SD60	RP	SHOP MAINTENANCE	12/7/11	E. ESCALEN	1	TOILET TANK LEAKING
SD60	130	ELECTRICAL-DYNAMIC BRAKING	1/14/12	F CONCHA	1	DYNAMIC BRAKE BO
SD60	81	INSPECTION PAST DUE	12/26/11	SAN LUIS P	1	AN M06 INSPECTION WAS/IS SCHEDULED ON 12/26/2011 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	110	ELECTRICAL-CAB MISC.	3/8/12	A. CRUZ	1	PRIMER & START SWITCH HANDLE MISSING. (PERILLA DE SWITCH DE ARRANQUE FALTANTE).
SD60	30	CAB MISC	3/12/12	SUPERVISO	1	SANITARIO NO DESCARGA
SD60	81	INSPECTION PAST DUE	3/26/12	SAN LUIS P	1	AN M03 INSPECTION WAS/IS SCHEDULED ON 03/26/2012 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	10	AIR-AIR BRAKES	6/18/12	S. CHAVEZ	1	POOR HORN. (SILBATO DEFICIENTE)
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	6/18/12	C. CHAVEZ	1	ENGINE SHUTDOWN, FUEL PUMP NOT WORKING. (SE MATÓ MD Y BOMBA DE COMBUATIBLE NO TRABAJA).
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	6/24/12	P. SAAVEDR	1	SE MATO MOTOR DIESEL SIN CAUSA APARENTE
SD60	81	INSPECTION PAST DUE	7/3/12	SAN LUIS P	1	AN M12 INSPECTION WAS/IS SCHEDULED ON 07/03/2012 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	10	AIR-AIR BRAKES	2/7/13	SUPERVISO	1	FUGA LEVE EN TUERCA UNION DE TUBERIA DE DEPOSITO PPAAL
SD60	170	ELECTRICAL-NO LOAD	2/10/13	MAYORDO	1	NO TIENE EXCITACION EN POTENCIA
SD60	350	TRUCK MISC.	2/18/13	L. CELEDON	1	QUEMADURAS EN MANCUERNAS 2 Y 5 ASI LA RECIBIO
SD60	30	CAB MISC	2/21/13	MA MORAL	1	WC NO DESCARGA
SD60	81	INSPECTION PAST DUE	3/6/13	MONTERRE	1	AN M03 INSPECTION WAS/IS SCHEDULED ON 03/06/2013 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	130	ELECTRICAL-DYNAMIC BRAKING	3/16/13	L CELEDON	1	FRENO DINAMICO INOPERANTE
SD60	30	CAB MISC	3/19/13	J E BELTRAN	1	ALERTOR SENTRY SE ACTIVA AUN ESTANDO DETENIDO Y APLICADO Y FAROLAS SUPERIORES PARTE DEL FRENTE NO FUNCIONAN
SD60	350	TRUCK MISC.	3/25/13	I CANCHOL	1	A REVISION DE MANCUERNAS MOTRICES DE TRUCK # 1 POR RUIDO TIPO APLANADURA
SD60	110	ELECTRICAL-CAB MISC.	3/30/13	G. PEREZ	1	ALERTOR SENTRY SE ACTIVA ESTANDO LOS FRENOS APLICADOS

SD60	10	AIR-AIR BRAKES	MINOR	4/9/13	MAQUINIST	1 FUGA EN ALVUAL MU DP POSTERIOR IZQUIERDA
SD60	300	NO START	MAJOR	4/22/13	MAQUINIST	1 NO ARRANCA MOTOR DIESEL
SD60	350	TRUCK MISC.	MINOR	5/23/13	F VIVEROS	1 SEIS ZAPATAS DE FRENO MUY DESGASTADAS
SD60	30	CAB MISC	MINOR	5/28/13	AMARQUEZ	1 APT MAL ORDEN
SD60	30	CAB MISC	MINOR	5/31/13	G RIVERA	1 GUIADA SE ACTIVA ALERTOR QUANTUM
SD60	81	INSPECTION PAST DUE	MAJOR	6/9/13	MONTERRE	1 AN M06 INSPECTION WAS/IS SCHEDULED ON 06/07/2013 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	390	WHEELS-WHEEL TRUE NEEDED	MINOR	7/17/13	MAYORDON	1 A TALLER DE S L P POR CAMBIO DE CAMBIO # 4
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	7/23/13	C H RODRIG	1 OSCILAMIENTO DE AMPERAJE SE PUNTO 2 AL 5 Y DEL 7 AL 8 SE CAE EL AMEPERAJE
SD60	81	INSPECTION PAST DUE	MAJOR	9/11/13	SAN LUIS P	1 AN M03 INSPECTION WAS/IS SCHEDULED ON 09/11/2013 AND IS PAST DUE OR HAS AN INSPECTION SCHEDULED WITHIN 3 DAYS OF THE SHOP DATE
SD60	390	WHEELS-WHEEL TRUE NEEDED	MINOR	9/14/13	R VILLAREA	1 MANCUERNA MOTRIZ # 4 A TORNO POR CEJA DELGADA
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	10/9/13	H DOMINGI	1 CABLES DE MOTOR DE TRACCION # 6 TROZADOS
SD60	30	CAB MISC	MINOR	10/20/13	PROVEDO	1 SE TRASMINA EL AGUA A LA CABINA DE OPERADOR
SD60	350	TRUCK MISC.	MINOR	11/13/13	R GOMEZ	1 ZAPATA DE FRENO # 1 DERECHA FALTANTE
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	11/13/13	R GOMEZ	1 MOTOR DETRACCION # 1 CORTADO, OPERA RELEVADOR DE TIERRA EN PUNTOS # 7 Y 8
SD60	RP	SHOP MAINTENANCE	Information	12/1/13	R IZAGUIRR	1 AN M03 INSPECTION WAS/IS SCHEDULED ON 12/16/2013
SD60	9020	WI-TRONIX	Information	12/2/13	C LEAL	1 CHECK WI-TRONIX SYSTEM FOR UNIT OUT OF CONTACT (REVISAR SISTEMA WI-TRONIX POR UNIDAD FUERA DE CONTACTO)
SD60	170	ELECTRICAL-NO LOAD	MAJOR	1/25/14	R QUINTERO	1 EN CAMBIO DE CONTROLES SE BOTO TERMICO REV CONTROL Y YA NO CIERRA.
SD60	30	CAB MISC	MINOR	1/31/14	G ROMAN	1 FALTA 1 ASIENTO LADO CONDUCTOR
SD60	110	ELECTRICAL-CAB MISC.	MINOR	2/6/14	MAQUINIST	1 VELOCIMETRO DESAJUSTADO Y MOTOR DIESEL SE AHOGA EN EL PUNTO # 2
SD60	110	ELECTRICAL-CAB MISC.	MINOR	2/12/14	MAYORDON	1 VELOCIMETRO DESAJUSTADO
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	2/13/14	MAYORDON	1 FUGA DE AGUA POR MANGUERA ROTA QUE CONECTA AL TANQUE DE EXPANSION
SD60	RP	SHOP MAINTENANCE	Information	3/20/14	R IZAGUIRR	1 AN M12 INSPECTION WAS/IS SCHEDULED ON 03/13/2014
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	3/30/14	B MENA	1 PARO DE MOTOR DIESEL POR BAJA PRESION DE ACEITE
SD60	300	NO START	MAJOR	4/2/14	MAQUINIST	1 NO ARRANCA MOTOR DIESEL
SD60	60	DERALMENT/ACCIDENT-MINOR	MINOR	4/4/14	M. ALMAGL	1 ACCIDENTADA ARROLLO A UN TRAILER CILINDRO DE FRENO # 3 LADO IZQUIERDO ROTO
SD60	390	WHEELS-WHEEL TRUE NEEDED	MINOR	4/8/14	MAYORDON	1 MANCUERNA MOTRIZ # 3 A TORNO Y COMBO # 4 MAL ORDEN
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	4/15/14	M TELLEZ	1 OPERA RELEVADOR DE TIERRA GR
SD60	300	NO START	MAJOR	4/27/14	J.BLANCO	1 MOTOR DIESEL SE APAGO POR PROTECCION NO ARRANCA LLEGARA A ESCOBEDO
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	5/8/14	G PEREZ	1 SE PARA MOTOR DIESEL SIN MENSAJE DE FALLA, OPERA RELEVADOR BDR
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	5/21/14	M A LUCIDC	1 OPERA RELEVADOR DE TIERRA GR EN EL # 3
SD60	320	SCHEDULED MAINTENANCE	Information	5/28/14	FMOCTEZUI	1 INGRESARLA A INSPECCION DE PROGRAMA M03 EL DIA 24/06/2014
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	5/30/14	J. B. LOPEZ	1 OPERA RELEVADOR DE TIERRA "GR" EN POTENCIA DESDE EL PUNTO # 5
SD60	300	NO START	MAJOR	6/22/14	MAYORDON	1 NO ARRANCA MOTOR DIESEL
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	6/23/14	H. DELGADI	1 SE MATO MOTOR DIESEL SIN CAUSA APARENTE
SD60	370	WHEELS-COMDEMABLE FLAT SPOTS	MAJOR	6/25/14	J SAUCEDO	1 CAMBIO DE MANCUERNAS MOTRICES EN GENERAL POR VIDA UTIL
SD60	10	AIR-AIR BRAKES	MINOR	7/8/14	PROVEEDO	1 FALLA EN SISTEMA DE FRENOS DE AIRE COMO GUIADA SE CAMBIA A GUIA COMUNICADA
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	7/12/14	H RODRIGU	1 PARO DE MOTOR DIESEL, MAQUINISTA COMENTA QUE LE OPERARON TODOS LOS DISPOSITIVOS DE PROTECCION, SE ESPERO UN RATO PARA QUE PUDIOERA ARRANC
SD60	20	AIR-AIR COMPRESSOR	MINOR	7/12/14	H RODRIGU	1 SILBATO DEFICIENTE Y BOTON ACCIONADOR FLOJO
SD60	30	CAB MISC	MINOR	8/13/14	J BLANCO	1 FAROLAS SUPERIORES FUNDIDAS PARTE DEL FRENTE
SD60	201	ELECTRICAL-WEAK BATTERIES-DEAD	MAJOR	8/19/14	F A LOPEZ	1 NO ARRANCA EL MOTOR DIESEL POR BATERIAS DEBILES
SD60	300	NO START	MAJOR	8/24/14	PROVEEDO	1 NO TRABAJA MOTOR BOMBA DE COMBUSTIBLE
SD60	320	SCHEDULED MAINTENANCE	Information	8/27/14	R IZAGUIRR	1 INGRESARLA A INSPECCION DE PROGRAMA M06 EL DIA 29 DE SEPTIEMBRE 2014
SD60	150	ELECTRICAL-LIGHTING	MINOR	9/10/14	J M CARRE	1 FAROLA DE REGUERA LADO IZQUIERDA FUNDIDA
SD60	30	CAB MISC	MINOR	9/15/14	R MARQUE	1 RADIO DE COMUNICACION BO, SE TOMO PARA KCSM-3842
SD60	110	ELECTRICAL-CAB MISC.	MINOR	9/18/14	H RODRIGU	1 SE BOTA TERMICO DEL SILBATO DE SEÑALES
SD60	20	AIR-AIR COMPRESSOR	MINOR	9/28/14	R IZAGUIRR	1 OCT.01.2014 PYS. LA ENTREGO Y SE DESCONOCE SI SE REALIZAR PRUEBA DE ORIFICIO (EFICIENCIA) A COMPRESOR DE AIRE, REPORTAN NO COMPLETA LAS PRESION C
SD60	201	ELECTRICAL-WEAK BATTERIES-DEAD	MAJOR	11/23/14	B. A. RUIZ	1 NO ARRANCA MOTOR DIESEL POR TENER LAS BATERIAS DEBILES
SD60	RP	SHOP MAINTENANCE	Information	12/1/14	C LEAL	1 INGRESAR A INSPECCION DE PROGRAMA M03 EN DIC 26 2014
SD60	10	AIR-AIR BRAKES	MINOR	12/2/14	UJSR03	1 REPORTA CONDUCTOR QUE SE DEJÓ 39 UNIDADES VACÍAS EN PK-V-391, DESPUÉS DE DEJAR LAS UNIDADES OPERADO FRENOS DE AIRE EN EMERGENCIA, SE AVANZÓ.
SD60	100	ELECTRICAL-CAB DISPLAY	MINOR	12/30/14	C LEAL	1 PROBAR FUNCIONAMIENTO DE HVAC Y REPORTAR FUNCIONAMIENTO TANTO EN FRIO/CALOR

SD60	150	ELECTRICAL-LIGHTING	MINOR	1/12/15	JOSE CARRE	1	FAROLA DE REGUERA LADO IZQUIERDO FUNDIDA
SD60	10	AIR-AIR BRAKES	MINOR	1/18/15	D GONZALE	1	SILBATO DE SEÑALES DEJO DE FUNCIONAR
SD60	30	CAB MISC	MINOR	1/20/15	TRIPULACI	1	RADIO DE COMUNICACION FALTANTE, ASI SE RECIBIO
SD60	110	ELECTRICAL-CAB MISC.	MINOR	2/8/15	R. GOMEZ	1	APARATO PRINCIPIO DE TREN NO TRABAJA Y RADIO TRANSMISOR FALTANTE
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	2/23/15	A. RUGERIC	1	OPERAN DISPOSITIVOS DE DE BAJA PRESION DE AGUA Y ACEITE
SD60	320	SCHEDULED MAINTENANCE	Information	3/6/15	F MOCTEZU	1	INGRESARLA A INSPECCION DE PROGRAMA M12 EL DIA 13 MARZO 2015
SD60	60	DERAILMENT/ACCIDENT-MINOR	MINOR	3/7/15	C L LOPEZ	1	DAÑADA DE LA PARTE DEL FRENTE POR AROOLLAMIENTO A VEHICULO
SD60	170	ELECTRICAL-NO LOAD	MAJOR	9/28/15	B.,QUEZAD	1	VOLTAJE LIMITADO POR ENFRIAMIENTO DE MOTOR DE TRACCION SE MANEJA REMOLCADA
SD60	30	CAB MISC	MINOR	10/2/15	A ALMAZAN	1	ESPEJO RETROVISOR LADO DERECHO ESTRELLADO POR VANDALISMO
SD60	30	CAB MISC	MINOR	10/5/15	R. BAUTIST	1	BAÑOS SUCIOS.
SD60	140	ELECTRICAL-GROUND RELAY (TCC C/O NO HELP)	MAJOR	10/21/15	J. GAYTAN	1	OPERA GR EN POTENCIA SE ANULARON TODOS LOS MOTORES DE TRACCION CONTINUANDO LA FALLA
SD60	140	ELECTRICAL-GROUND RELAY (TCC C/O NO HELP)	MAJOR	10/25/15	SUPERVISO	1	OPERA GR
SD60	170	ELECTRICAL-NO LOAD	MAJOR	10/31/15	E. CERNA	1	OPERA GR EN PUNTO #5 DEL REGULADOR.
SD60	30	CAB MISC	MINOR	11/9/15	M.A. MORA	1	SANITARIO NO FUNCIONA
SD60	20	AIR-AIR COMPRESSOR	MINOR	11/9/15	M. MORALE	1	FUGA CONSTANTE EN VALVULA DE SEGURIDAD DE DEPOSITO PRINCIPAL Y SE BOTA EL DISPOSITIVO DEL GOBERNADOR
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	12/4/15	MAYORDOM	1	CAMBIO DE CLUTCH DEL TURBO
SD60	320	SCHEDULED MAINTENANCE	Information	12/26/15	I RAIGOZA	1	REALIZAR INSPECCION DE PROGRAMA M03 EL DIA 06/01/16
SD60	270	FRA WORKING TO SHOP	MINOR	11/11/16	E. VALLEJO	1	NO USAR COMO GUÍA, GRABADORA DE EVENTOS MAL ORDEN
SD60	320	SCHEDULED MAINTENANCE	Information	12/22/16	CAGUINAG	1	INGRESA A INSP M06 EL 11 ENERO 2017 EN TALLER DE SLP
SD60	130	ELECTRICAL-DYNAMIC BRAKING	MINOR	1/8/17	J MARTINEZ	1	OPERA PATINAMIENTO EN FRENO DINAMICO A PARTIR DEL PUNTO #4
SD60	270	FRA WORKING TO SHOP	MINOR	1/27/17	ENRIQUE V	1	ER DATA INVALID IN ASSET SAMPLE
SD60	270	FRA WORKING TO SHOP	MINOR	3/10/17	E VALLEJO	1	NO DESCARGA ARCHIVOS EL REGISTRADOR
SD60	300	NO START	MAJOR	3/1/17	SUPERVISO	1	DAÑOS EN SEGMENTO DENTADO DEL VOLANTE DE INERCIA
SD60	30	CAB MISC	MINOR	3/17/17	FERNADNO	1	CONECTOR DE RADIO DE COMUNICACIONES MAL ORDEN NO ALIMENTA RADIO
SD60	270	FRA WORKING TO SHOP	MINOR	3/29/17	ENRIQUE O'	1	NO USAR COMO LIDER O GUIA FALLA DE LA GRABADORA DE EVENTOS
SD60	320	SCHEDULED MAINTENANCE	Information	3/29/17	CAGUINAG	1	INGRESAR A INSP M03 EL 07 ABRIL 2017 TALLER SLP
SD60	30	CAB MISC	MINOR	6/21/17	A ALMANZA	1	REPORTAN NO CIENE UN MONITOR EN CABINA
SD60	320	SCHEDULED MAINTENANCE	Information	6/30/17	CAGUINAG	1	INGRESAR A INSP M12 EL 18 JUL 2017 EN TALLER SLP
SD60	210	ENGINE RELATED FAILURE (SHUTDOWNS)	MAJOR	7/14/17	SUPERVISO	1	SE APAGA MOTOR DIESEL, POR PERDIDA DE PRESION DE COMBUSTIBLE, MARCA LECTURAS ERRONEAS
SD60	50	CARBODY	MINOR	7/14/17	ANTONIO A	1	SE MUEVE LA CARÁTULA MARCANDO MÁS DE LO QUE TRAE DE COMBUSTIBLE SE REQUIERE QUE SE CORRIJA ESTE DEFECTO QUE TIENE EN MANOMENTRO DE COMBUS
SD60	170	ELECTRICAL-NO LOAD	MAJOR	8/6/17	CRSTOFER E	1	CARGA LIMITADA SE CORTA EL AMPERAJE EN EL PUNTO # 2
SD60	30	CAB MISC	MINOR	8/9/17	HELP DESK	1	EVENT RECORDED FAILED IS NOT COMMUNICATING
SD60	170	ELECTRICAL-NO LOAD	MAJOR	12/27/17	ANTONIO A	1	SE CORTA DEL SERVICIO POR CAJA MOTRIZ LADO DERECHO CALIENTE APARENTEMENTE FALTA DE LUBRICACION
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	1/15/18	SUP DE QUE	1	SE ACTIVA ALARMA Y SE CORTA EL AMPERAJE,
SD60	350	TRUCK MISC.	MINOR	2/1/18	JUAN JOSE C	1	FRENO DE MANO INOPERANTE
SD60	20	AIR-AIR COMPRESSOR	MINOR	2/12/18	PROVEEDO	1	SILBATO INOPERANTE
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	4/3/18	PROVEEDO	1	NO LEVANTA EXITACION MARCHA ATRAS
SD60	150	ELECTRICAL-LIGHTING	MINOR	4/3/18	PROVEEDO	1	FAROLA DE REGUERA FUNDIDA
SD60	220	ENGINE SUPPORT (FUEL/OIL/WATER LEAKS, ETC...)	MEDIUM	4/5/18	SUPERVISO	1	REPORTA SUPERVISOR FUGA DE AGUA NO ESPECIFICA EL LUGAR.
SD60	30	CAB MISC	MINOR	4/13/18	OPERARIO C	1	LLEGO A CIL Y NO CUENTA CON RADIO NI APARATO PRINCIPIO DE TREN
SD60	30	CAB MISC	MINOR	4/23/18	JA LARA TEL	1	AIRE ACONDICIONADO NO ENFRIA, NECESARIO SALGA TRABAJANDO CORRECTAMENTE, LOCOMOTORA ASIGNADA EN TAMPICO
SD60	30	CAB MISC	MINOR	4/23/18	LARA TELL	2	VELOCIMETRO DESAJUSTADO A 30KM/HR MARCA 60 MPH
SD60	130	ELECTRICAL-DYNAMIC BRAKING	MINOR	4/25/18	JESUS SIFU	1	OPERA PATINAMIENTO EN FRENO DINAMICO EL # DEL TH DE PD
SD60	160	ELECTRICAL-LITE LOAD	MEDIUM	5/16/18	LARA TELL	1	OPERA PATINAMIENTO DE RUEDA EN FRENO DINAMICO PUNTO4
SD60	140	ELECTRICAL-GROUND RELAY (TCC C/O NO HELP)	MAJOR	7/18/18	SUP DE DOÍ	1	OPERA GR EN POTENCIA
SD60	170	ELECTRICAL-NO LOAD	MAJOR	7/26/18	UEOM10	1	KCSM3813 NO TIENE AMPERAJE
SD60	50	CARBODY	MINOR	7/31/18	EMD SLP	1	FRENO DE MANO SE QUEDA TRABADO
SD60	RP	SHOP MAINTENANCE	Information	8/13/18	GAA	1	FLANGE LUBE APPLICATOR SURVEY: AUDIT FOR LUBE STICK APPLICATORS. ONLY PUT YES OR NO IN COMMENTS AND CLOSE DEFECT.
SD60	280	LAB CODE-ENGINE IS SHUTDOWN	MAJOR	9/5/18	SUPERVISO	1	SUPERVISOR EN TURNO REPORTA FUGA EN BOMBA DEL S/E MD LADO IZQUIERDO ENVIAR REMOLCADA A S.L.P.
SD60	9020	WI-TRONIX	Information	10/3/18	DHILL@WI	1	WI-PU NO COMMUNICATION: TROUBLE SHOOT WI-PU OUT OF CONTACT. USE TROUBLESHOOTING GUIDE PROVIDED TO SHOP MANAGERS
SD60	280	LAB CODE-ENGINE IS SHUTDOWN	MAJOR	10/16/18	GILBERTO F	1	SE APAGO POR BOMBA DE AGUA BO
SD60	230	EOT/HOT COMMUNICATION	MINOR	10/28/18	SUPERVISO	1	FALLA DE COMUNICACION CON RADIO
SD60	30	CAB MISC	MINOR	11/4/18	RAUL CARD	1	VELOCIMETRO MAL ORDEN
SD60	30	CAB MISC	MINOR	11/4/18	UEOM10	2	REPORTA TRIPULACION QUE LOC. KCSM-3813 NO MARCA VELOCIMETRO, SE CAMBIÓ LOCOMOTORA POR KCSM-3928
SD60	30	CAB MISC	MINOR	1/31/19	MARTIN FEI	1	REPORTA INSPECTOR DE MAQUINISTAS QUE LA GUARDA DE LAMINA QUE SUJETA EL PLASTICO DEL PISO DE LA LOCOMOTORA ESTA LEVANTADA FAVOR DE ATENDERL
SD60	70	DERAILMENT/ACCIDENT-MAJOR	MAJOR	2/7/19	ANTONIO A	1	REPORTA MAYORDOMO DE SITIO QUE LOCOMOTORA SUFRIO ACCIDENTE EN PATIO POR ALCANZE DE OTRA LOCOMOTORA DAÑANDO LA POSICION DE BATERIAS, A
SD60	RP	SHOP MAINTENANCE	Information	2/15/19	CAGUINAG	1	ENVIAR A TALLER SLP. INSP FEDERAL EFECTUADA EN L. CARDENAS. PENDIENTE COMPLETAR INSPECCION M12 DEL 23 DE ENERO 2019

RESET.

AR DE NUEVO, FALLA REPETITIVA EL 23/06/14, NO SE LE ENCONTRO DEFE

DE DEPOSITO PRINCIPAL, FUE RECIBIDA POR F. MOCTEZUMA

A PK-V-398 OPERANDO NUEVAMENTE LA EMERGENCIA, SE RETROCEDIÓ /

TIBLE

A PARA EVITAR ACCIDENTES
COPLADOR Y SU MUELA FRONTAL, Y LUCES DE REGUERA