

Locomotive Annual Inspection Report (supplement to 92 day form)

Burlington Jct rwy

Po Box 37

Burlington, Ia 52601

Unit No. MVPX 1207

Location: Burlington, IA

Date: 01-05-12

1. Inspect crank case (including AP@ pipes & crank shaft thrust)	JB
2. Check load meter	JB
3. Clean, oil & test control air pressure regulator (adjust to 90.PSI)	JB
4. Renew filters & dirt collectors	JB
5. Test operation of emergency brake valve	JB

Air Box Inspection

Cyl	Piston	Rings	Liner	Lead	Land	Comp
1.	Ok	Ok	Ok	.059/.060	<.010	340
2.	Ok	Ok	Strkd	.073/.077	<.010	320
3.	Ok	Ok	glazed	.071/.076	<.010	300
4.	Ok	Ok	glazed	.057/.059	<.010	320
5.	Ok	Ok	glazed	.061/.062	<.010	300
6.	Ok	Top and bottom rings are slick	Strkd	.086/.087	<.010	310
7.	Ok	Ok	strkd	.066/.069	<.010	340
8.	Ok	Ok	strkd	.060/.065	<.010	330
9.	Ok	Ok	strkd	.067/.069	<.010	310
10.	Ok	Ok	Ok	.071/.076	<.010	330
11.	Ok	Ok	Strkd	.072/.074	<.010	315
12.	Ok	Ok	Strkd	.055/.059	<.010	310
13.						
14.						
15.						
16.						

Signed: D Sandefur

